

**JLK sp. z o.o. sp.k.**

**ul. Zagnańska 12, 25-524 Kielce, NIP: 959-163-63-02**

**tel. 041 341 55 24, 0506 172 722, e-mail: mariusz@jlk.com.pl**

LP	VEGGA No.	ZASTOSOWANIE	TRW No.	ATE No.	OPIS ZESTAW ZNAJDUJĄCY SIĘ W KOLCKACH HAM. NR. QUICK BRAKA – tylko dla porównania
1	33001	Opel Astra F, Opel Corsa B ; Opel Vectra A	GDB1040	13.0463-7051.2	
2	33002	VW Golf III	GDB1218	13.0460-7072.2	
3	33003	Fiat CQN	GDB1299	13.0460-3950.2	
4	33004	VW Passat ; Skoda ; Audi A6	GDB1307	13.0460-7110.2	z czujnikiem
5	33005	VW Golf III ; Seat Ibiza II , III ; Ford Focus	GDB1437	13.0460-2821.2	
6	33006	Fiat Punto z czuj.	GDB1291	13.0460-7114.2	z czujnikiem
7	33007	Ford Escort	GDB1349	13.0460-3965.2	
8	33008	Renault Laguna 93->	GDB1030	13.0460-2983.2	z czujnikiem
9	33009	Renault Laguna 93->	GDB1332	13.0460-2834.2	
10	33010	Ford Escort	GDB1349	13.0460-3965.2	z czujnikiem akustycznym
11	33011	Opel Corsa C; Meriva	GDB1570	13.0460-2857.2	z zest.mont., ( 109-1246 )
12	33012	Opel Astra G	GDB1351	13.0460-7115.2	
13	33013	Opel Astra F ; Opel Vectra B ; Opel Vectra A	GDB951	13.0463-7052.2	
14	33014	Opel Vectra B	GDB915	13.0460-4040.2	z zest.mont., ( 109-1266 )
15	33015	VW Golf IV , AUDI, Skoda	GDB1357	13.0460-7111.2	
16	33016	Citroen Saxo	GDB327	13.0460-3911.2	z czujnikiem
17	33017	Daewoo Lanos, Matiz	GDB3195	13.0460-5996.2	
18	33018	Opel Vectra B ; Saab	GDB1271	13.0460-7091.2	
19	33019	Opel Omega B 2.0 16V	GDB1166	13.0460-7080.2	
20	33020	Opel Asta G ; Opel Zafira ;	GDB1350	13.0463-7116.2	z czujnikiem akustycznym
21	33021	Opel Omega B	GDB1302	13.0460-4040.2	
22	33022	Opel Omega B	GDB957	13.0460-2815.2	
23	33023	Opel Kadett, Vectra A	GDB199	13.0460-7048.2	
24	33024	Opel Astar G ; Opel Zafira	GDB1471	13.0460-3976.2	z zest.mont. (109-1245)
25	33025	Opel Astar G ; Opel Zafira	GDB1515	13.0460-2868.2	z zest.mont. (109-1245 + 4 śruby)
26	33025 E	Opel Astar G ; Opel Zafira	GDB1515	13.0460-2868.2	

Arkusz1

27	33026	Fiat Uno	GDB297	13.0460-3940.2	
28	33027	Fiat CQN	GDB1299	13.0460-3950.2	
29	33028	Ford Fiesta 89-00	GDB953	13.0460-7073.2	
30	33029	Ford Mondeo 93→ z czuj.	GDB1108	13.0460-7060.2	z czujnikiem
31	33030	Ford Mondeo 93-> tyl z czuj.	GDB1112	13.0460-3964.2	z czujnikiem
32	33031	Ford Focus 98->	GDB1358	13.0460-7121.2	
33	33032	Audi 80 86-90	GDB826	13.0460-2958.2	
34	33033	VW Golf III ; Seat Cordoba	GDB1044	13.0460-2958.2	
35	33034	VW T4	GDB1092	13.0460-2982.2	
36	33035	VW Golf IV ; Seat Leon ; Audi	GDB1330	13.0460-2820.2	z zest.mont. (109-1211 + 4 śruby)
37	33035 E	VW Golf IV ; Seat Leon ; Audi	GDB1330	13.0460-2820.2	
38	33036	VW T4	GDB862	13.0460-2972.2	
39	33037	VW Golf III ; Seat Ibiza II	GDB454	13.0463-7032.2	
40	33038	VW T4 tył z czuj.	GDB1369	13.0460-2874.2	Z czujnikiem,z zest.mont. (109-1233 + 4 śruby)
41	33039	VW T4 „kwadrat”	GDB791	13.0460-2973.2	
42	33040	VW Golf II 83->	GDB463	13.0460-7030.2	
43	33041	Citroen Xsara Picasso 00->	GDB1295	13.0460-2862.2	z czujnikiem
44	33042	VW Golf IV ; Audi A3 ; Seat Toledo	GDB1386	13.0460-7117.2	z czujnikiem
45	33043	Ford Transit 91-98	GDB1084	13.0460-3960.2	z zest.mont. (109-1145)
46	33044	VW Passat ; Audi A4 ; Seat	GDB1366	13.0460-2837.2	z czujnikiem
47	33045	Audi 100, A6	GDB1049	13.0460-7050.2	z czujnikiem
48	33046	VW Golf IV	GDB1403	13.0460-7122.2	z czujnikiem
49	33047	VW Polo 96-01	GDB1274	13.0460-7100.2	
50	33048	Renault Clio I	GDB807	13.0460-2955.2	z czujnikiem
51	33049	Audi 100 ; Audi 80 ; Audi A4 tył	GDB1163	13.0460-3602.2	
52	33050	Peugeot 206 98->	GDB1500	13.0460-3975.2	z zest.mont. (109-1218)
53	33051	VW T4 95->	GDB1391	13.0460-7102.2	z czujnikiem
54	33052	VW T4	GDB1092	13.0460-2982.2	z czujnikiem
55	33053	Opel Vectra C ; Ford Focus II	GDB1621	13.0460-7194.2	
56	33054	Citroen Berlingo 01->	GDB1563	13.0460-3994.2	z zest.mont. (109-1218)
57	33056	Ford Fiesta 02->	GDB1419	13.0460-7142.2	
58	33057	Ford Fiesta 08->	GDB3437	13.0460-5794.2	z czujnikiem akustycznym
59	33058	Ford Focus 98-> tyl	GDB1354	13.0460-2835.2	
60	33059	Ford Focus II	GDB1583	13.0460-7193.2	
61	33060	Ford Galaxy 06-> , Mondeo 07->	GDB1683	13.0460-7228.2	
62	33061	Ford Galaxy 06-> , Mondeo 07-> ( + elec ) tyl	GDB1685	13.0460-2722.2	

## Arkusz1

63	33062	Skoda Felicja	GDB1280	13.0460-2964.2	
64	33063	Ford Galaxy 06-> , Mondeo 07-> ( - elec ) tyl	GDB1732	13.0460-2723.2	4 śruby
65	33064	Ford Galaxy	GDB1538	13.0460-7121.2	z czujnikiem
66	33065	Ford Mondeo III 00->	GDB1434	13.0460-3987.2	z czujnikiem akustycznym
67	33066	Ford Mondeo III tyl ->04	GDB1525	13.0460-3988.2	z czujnikiem akustycznym
68	33067	Ford Mondeo III tyl 04-07	GDB1665	13.0460-3831.2	
69	33068	Ford Transit 00->	GDB1461	13.0460-3992.2	z czujnikiem akustycznym
70	33069	Ford Transit 00->	GDB1424	13.0460-3993.2	z czujnikiem akustycznym
71	33070	Ford Transit 06->	GDB1723	13.0460-3833.2	Z czujnikiem, z zest.mont. (109-1298 + 2 śruby)
72	33071	Ford Transit 06->	GDB1724	13.0460-3834.2	Z czujnikiem, z zest.mont. (109-1298 + 2 śruby)
73	33072	Peugeot 206 1.1 98->	GDB1361	13.0460-3975.2	
74	33073	Peugeot 306	GDB1104	13.0460-7058.2	z czujnikiem
75	33074	Peugeot 307	GDB1463	13.0460-3994.2	
76	33075	Peugeot 307	GDB1464	13.0460-3811.2	z zest.mont. (109-1298))
77	33076	VW Sharan ; Seat Alhambra ; Ford Galaxy	GDB1440	13.0460-7143.2	z czujnikiem
78	33077	Peugeot 406	GDB1193	13.0460-2816.2	z czujnikiem
79	33078	Peugeot 406	GDB1194	13.0460-2817.2	z czujnikiem
80	33079	Peugeot 406 tyl	GDB1276	13.0460-4059.2	
81	33080	Peugeot 407	GDB1594	13.0460-2891.2	z czujnikiem
82	33081	Peugeot 407 tyl	GDB1596	13.0460-2893.2	
83	33082	VW Polo ; Skoda Fabia ; Seat Ibiza	GDB1472	13.0460-2884.2	z czujnikiem
84	33083	Peugeot Boxer 06->	GDB1681	13.0460-2722.2	Z czujnikiem, z zest.mont. (109-1725 +4 śruby + 4 kapturki)
85	33084	Peugeot Boxer 06->	GDB1703	13.0460-4810.2	Z czujnikiem, z zest.mont. (109-1725 +4 śruby + 4 kapturki)
86	33085	Peugeot Boxer 06-> tyl	GDB1682	13.0460-4812.2	z zest.mont. (109-1218 + 2 śruby)
87	33086	Peugeot Boxer 02->	GDB1517	13.0460-4978.2	z czujnikiem
88	33087	VW Golf IV ; Audi A3 ; Skoda Octavia	GDB1550	13.0460-7184.2	z czujnikiem
89	33088	Peugeot Boxer 02->	GDB1518	13.0460-4979.2	
90	33089	VW Transporter T5	GDB1555	13.0460-7236.2	z czujnikiem
91	33090	Peugeot Boxer 02-> tyl	GDB1521	13.0460-4980.2	z zest.mont. (109-1600 + 4 śruby + 4 kapturki)
92	33091	Mercedes Sprinter	GDB1220	13.0460-7196.2	
93	33092	Mercedes Sprinter	GDB1288	13.0460-7909.2	
94	33093	VW Polo ; Skoda Fabia ; Seat Ibiza	GDB1586	13.0460-7164.2	z czujnikiem
95	33094	Mercedes Sprinter tyl	GDB1262	13.0460-7083.2	z czujnikiem
96	33095	Mercedes Sprinter tyl	GDB1263	13.0460-7084.2	z czujnikiem
97	33096	Mercedes Sprinter tyl	GDB1399	13.0460-3990.2	z czujnikiem
98	33097	Fiat Brava, Bravo, Marea	GDB1290	13.0460-7065.2	z czujnikiem

## Arkusz1

99	33098	VW Passat ; Seat Leon ; Audi A3	GDB1616	13.0460-7200.2	z czujnikiem
100	33099	VW Passat B6 ; Golf V ; Audi A6 tyl	GDB1622	13.0460-2880.2	z zest.mont. (109-1606 + 4 śruby)
101	33100	Fiat Doblo	GDB1655	13.0460-3827.2	z czujnikiem
102	33101	Fiat Grande Punto	GDB1654	13.0460-3826.2	z czujnikiem
103	33102	Opel Astra H ; Opel Astra G, Opel Corsa C	GDB1668	13.0460-7179.1	z czujnikiem
104	33103	Fiat Panda	GDB1589	13.0460-3809.2	
105	33104	Renault Clio II	GDB1465	13.0460-2834.2	z czujnikiem i z 2 śrubami
106	33105	Renault Clio II tyl	GDB1305	13.0460-3823.2	z zest.mont. (109-1125)
107	33106	Renault Kango 97->	GDB1402	13.0460-3977.2	
108	33107	Renault Kango 04->	GDB1552	13.0460-3815.2	
109	33108	Opel Vectra C ; Opel Signum	GDB1686	13.0460-7172.1	
110	33109	VW Crafter ; Mercedes Sprinter	GDB1697	13.0460-3832.2	Z czujnikiem, z zest.mont. (109-1218 + 2 śruby)
111	33110	VW Crafter ; Mercedes Sprinter	GDB1698	13.0460-4826.2	z czujnikiem + 4 śruby + 4 kapturki)
112	33111	Opel Corsa D	GDB1700	13.0460-3839.1	z zest.mont. (109-1716 + 2 śruby)
113	33112	Renault Laguna 93-> tyl	GDB1353	13.0460-4986.2	
114	33113	Renault Laguna II	GDB1468	13.0460-7158.2	
115	33114	Renault Laguna II	GDB1540	13.0460-7157.2	z zest.mont. (109-1187)
116	33115	Opel Vectra C	GDB1469	13.0460-7160.1	
117	33116	Renault Master II	GDB1442	13.0460-3800.2	
118	33117	Renault Master II	GDB1380	13.0460-3946.2	
119	33118	Renault Master II tyl	GDB1470	13.0460-3806.2	
120	33119	Renault Megane II	GDB1687	13.0460-7221.2	z zest.mont. (109-1187)
121	33120	Renault Trafic 01->	GDB1478	13.0460-2870.2	
122	33121	Ford Mondeo ; Ford Cougar	GDB1580	13.0460-3963.2	
123	33122	Ford Transit 15"	GDB1080	13.0460-3959.2	
124	33123	Fiat Doblo ; Palio Weekend	GDB1443	13.0460-7141.2	
125	33124	Fiat Doblo 01->	GDB1588	13.0460-7141.2	
126	33125	Citroen Jumper 94->; Fiat Ducato 94->	GDB1105	13.0460-2976.2	z czujnikiem
127	33126	Citroen Jumper 94->; Fiat Ducato 94->	GDB1425	13.0460-2825.2	z czujnikiem
128	33127	Citroen Jumper 94->; Fiat Ducato 94->	GDB1106	13.0460-2977.2	z czujnikiem
129	33128	Fiat Bravo / Brava ; Alfa Romeo 146	GDB1212	13.0460-7140.2	z czujnikiem
130	33129	Mercedes C ( W202)	GDB1094	13.0460-2975.2	
131	33130	Mercedes C ( W202 ) ; Mercedes E ( W210 )	GDB1205	13.0460-7086.2	
132	33131	Mercedes 190 ( W201 ) ; Mercedes C ( W202 )	GDB1130	13.0460-3504.2	
133	33132	Mercedes C ( W203 ) ; Mercedes CLK ( C209 )	GDB1413	13.0460-2726.2	
134	33133	Mercedes 190 ( W201 ) ; Mercedes E ( W124 )	GDB818	13.0460-2927.2	

## Arkusz1

135	33134	Mercedes 190 ( W201 ) ; Mercedes E ( W124 )	GDB911	13.0460-4034.2	
136	33135	Mercedes C ( W202 ) ; Mercedes E ( W210 )	GDB1335	13.0460-4064.2	
137	33136	Mercedes 190 ( W201 )	GDB817	13.0460-2923.2	2 śruby
138	33137	Mercedes Vito ; Mercedes V	GDB1373	13.0460-3980.2	
139	33138	Mercedes Vito ; Mercedes V	GDB1408	13.0460-3985.2	
140	33139	Mercedes Vito ( W639) 03-> ; Mercedes Viano (	GDB1601	13.0460-3821.2	
141	33140	Mercedes Vito ( W639) 03-> ; Mercedes Viano (	GDB1600	13.0460-3819.2	Z czujnikiem, z zest.mont. (109-1218 + 2 śruby)
142	33141	BMW 3 ( E36 ) ; BMW 3 ( E46 )	GDB1348	13.0460-5405.2	
143	33142	BMW 3 ( E36 ) ; BMW 3 ( E46 ) ; BMW 5 ( E34 )	GDB917	13.0460-3803.2	
144	33143	BMW 3 ( E36 ) ; BMW 3 ( E46 ) ; Rover 75	GDB1344	13.0460-3605.2	
145	33144	Citroen C4 04-> ; Peugeot 307 00->	GDB1620	13.0460-3813.2	
146	33145	BMW 5 ( E60 ) ; Peugeot 106 91-> ; Citroen C15	GDB1033	13.0460-3952.2	z czujnikiem
147	33146	Citroen Xsara 97-> ; Peugeot 206 98->	GDB1385	13.0460-3978.2	
148	33147	Renault Laguna 93-> ; Chrysler Viper 92->	GDB1041	13.0460-4957.2	
149	33148	Skoda Fabia 99-> ; Seat Ibiza IV 02-> ; VW Polo	GDB1414	13.0460-2883.2	
150	33149	Skoda Favorit	GDB473	13.0460-2912.2	
151	33150	Toyota Corolla 97-> ; Toyota Verso	GDB3288	13.0460-5815.2	z czujnikiem
152	33151	Toyota Corolla 01-> ; Toyota Verso	GDB3317	13.0460-5810.2	z czujnikiem
153	33152	Toyota Corolla 97-> ; Toyota Yaris 99->	GDB3243	13.0460-5812.2	z czujnikiem
154	33153	Toyota Avensis 03-> ; Corolla Verso 01->	GDB3336	13.0460-5813.2	z czujnikiem
155	33154	Toyota Avensis 97-> ; Corolla Verso 01->	GDB3337	13.0460-5814.2	z czujnikiem
156	33155	Toyota Avensis 97->	GDB3163	13.0460-5809.2	z czujnikiem
157	33156	Toyota Avensis 97-> ; Carina E 92->	GDB1145	13.0460-5845.2	
158	33157	Toyota Yaris	GDB3218	13.0460-5811.2	z czujnikiem
159	33158	Toyota Yaris 01->	GDB3324	13.0460-5800.2	z czujnikiem
160	33159	BMW 3 ( E30 ) ; BMW 3 ( E36 ) ;	GDB820	13.0460-2921.2	
161	33160	BMW 3 ( E46 ) ; BMW 5 ( E39 )	GDB1404	13.0460-7089.2	
162	33161	BMW 5 ( E39 ) ; ALPINA B10 ( E39 )	GDB1265	13.0460-7090.2	
163	33162	Ford Fiesta V 01-> ; Ford Focus 98->	GDB1532	13.0460-7186.2	
164	33163	Toyota Corolla 97-> ; Toyota Verso	GDB3289	13.0460-5819.2	jak w klockach TRW3289
165	33164	VW Golf III ; Seat Ibiza II, III, IV	GDB1306	13.0460-7101.2	
166	33165	VW Transporter T4 98-> ; Sharan 95->	GDB1460	13.0460-7153.2	z czujnikiem
167	33166	Citroen C5 01 → tył ; C5 Break	GDB1450	13.0460-4921.2	
168	33167	Citroen C5 01 → ; C5 Break	GDB1448	13.0460-3997.2	z czujnikiem
169	33168	Mercedes Klasa C 00-> ; Mercedes CLK 02->	GDB1545	13.0460-4064.2	
170	33169	Mercedes Klasa C 00-> tył ; Mercedes CLK 02->	GDB1421	13.0460-4065.2	jak w klockach ATE 13.0460-4065.2

Arkusz1

171	33170	Mercedes Klasa C 93-> tył ; Mercedes Klasa E 93	GDB987	13.0460-3805.2	
172	33171	KIA Cee'd 06-> ; Hyundai i30 07->	GDB3450	13.0460-5742.2	
173	33172	KIA Cee'd 06->	GDB3451	13.0460-5780.2	z zest.mont. (109-1708)
174	33173	Getz 02-> ; Hyundai Accent 94->	GDB3331	13.0460-5872.2	
175	33174	Honda Civic VIII 05-> ; Jaguar XK 06->	GDB3407	13.0460-5756.2	z zest.mont. (109-1707)
176	33175	Honda Civic VIII 06->	GDB3408	13.0460-5757.2	
177	33176	Audi 80 ; Audi A4 ; VW Passat 88->	GDB826	13.0460-2958.2	
178	33177	Peugeot 307 03->	GDB1605	13.0460-7202.2	
179	33178	Peugeot 407 04-> ; Citroen C5 08->	GDB1595	13.0460-2892.2	z czujnikiem
180	33179	Nissan Micra 03-> ; Renault Clio III 05->	GDB3332	13.0460-5801.2	4 śruby
181	33180	Volvo S40 95-> ; Mitsubishi Carisma 95->	GDB1313	13.0460-2853.2	z zest.mont. (109-1219)
182	33181	Volvo S40 95-> ; Mitsubishi Carisma 95->	GDB1314	13.0460-2897.2	z zest.mont. (109-1219)
183	33182	Volvo S60 00-> ; S80 98->	GDB1388	13.0460-7145.2	
184	33183	Volvo S60 00-> ; S80 98-> tył	GDB1389	13.0460-7135.2	
185	33184	Toyota Avensis 97-> ; Corolla 97->	GDB3334	13.0460-5869.2	jak w klockach TRW3334
186	33185	Toyota Corolla 97->	GDB3300	13.0460-5951.2	
187	33186	Toyota Corolla 97->	GDB3333		
188	33187	Ford Transit 06-> ; Ford Tourneo 06->, tył	GDB1725	13.0460-3835.2	z czujnikiem
189	33188	Opel Agila 08-> ; Suzuki Swift III 05->	GDB3396	13.0460-5700.2	
190	33189	Rover 200 -400 89>, Honda Civic 94->	GDB496	13.0460-2803.2	z czujnikiem
191	33190	Opel Vectra C 02-> , Opel Signum 03->	GDB1492	13.0460-7172.2	
192	33191	Peugeot 106 91->	GDB1031	13.0460-4042.2	z czujnikiem
193	33192	Renault Megane II 02->	GDB1571	13.0460-3814.2	z zest.mont. (109-1218 + 2 śruby)
194	33193	Renault Trafic 01-> , Opel Vivaro 01-> tył	GDB1479	13.0460-2840.2	
195	33194	Honda Civic 94->, Rover 200-400 90-> tył	GDB499	13.0460-5998.2	z czujnikiem
196	33195	Mercedes C – Klasa ( W202 ) 93->	GDB1283	13.0460-4060.2	
197	33196	Nissan Almera II 00->, Nissan Primera 96->	GDB3168	13.0460-5807.2	
198	33197	Nissan Almera II 00->, Nissan Primera 96-> tył	GDB3092	13.0460-5986.2	
199	33198	Nissan Primera 90->	GDB848	13.0460-5950.2	
200	33199	Mazda 626 91->	GDB1139	13.0460-5954.2	z czujnikiem
201	33200	Fiat Stilo 01->	GDB1483	13.0460-3983.2	z czujnikiem
202	33201	Fiat Panda 04->, Fiat Punto 99-> tył	GDB1384	13.0460-2879.2	
203	33202	Alfa Romeo 147 01-> , Alfa Romeo 156 00->	GDB1444	13.0460-7139.2	z czujnikiem
204	33203	Alfa Romeo 147 01-> , Alfa Romeo 156 00->	GDB1445	13.0460-7140.2	z czujnikiem
205	33204	Fiat Marea 96->, Alfa Romeo 146 94-> tył	GDB466	13.0460-2951.2	
206	33205	Alfa Romeo 156 97-> , Lancia Kappa 94-> tył	GDB1147	13.0460-2827.2	

Arkuszl

207	33206	BMW 3 ( E90 ) 05-> , BMW 1 ( E87 ) 04-> tył	GDB1612	13.0460-2713.2	z zest.mont. (109-1245 + 2 śruby)
208	33207	BMW 3 ( E90 ) 05-> , BMW 1 ( E87 ) 04-> tył	GDB1626	13.0460-7217.2	
209	33208	BMW 5 ( E60 ) 03-> , BMW 3 ( E90) 05->	GDB1559	13.0460-7176.2	
210	33209	Citroen C2 03-> , Citroen C3 02->	GDB1495	13.0460-2871.2	z zest.mont. (109-1242 + 2 śruby)
211	33210	Mercedes Sprinter 06-> , VW Crafter 06->	GDB1699	13.0460-3842.2	4 śruby
212	33211	Toyota Corolla 01-> ; Toyota Yaris 99->	GDB3242	13.0460-5810.2	
213	33212	Volvo S40, V40 95-> ,	GDB1317	13.0460-2830.2	
214	33213	BMW 5 E60 03-> ,BMW 6 E63 04->	GDB1727	13.0460-7174.2	
215	33214	Opel Movano 10-> , Renault Master III 10->	GDB1885	13.0460-4857.2	z czujnikiem
216	33215	Opel Movano 10-> , Renault Master III 10->	GDB1903	13.0460-4858.2	
217	33216	Opel Insignia 08-> , Saab 9-5 10->	GDB1784	13.0460-2755.2	z zest.mont. (109-1776)
218	33217	Toyota RAV 4 00->	GDB3251	13.0460-5848.2	
219	33218	Toyota rav 4 94-> , Toyota RAV 4 00->	GDB3279	13.0460-5849.2	
220	33221	Mercedes Sprinter 06-> , VW Crafter 06->	GDB1696	13.0460-4827.2	
221	33219	VW Touareg 02-> , Porsche Cayenne 02-> , Audi Q	GDB1548	13.0460-4993.2	z czujnikiem
222	33220	VW Touareg 02-> , Porsche Cayenne 02-> , Audi Q	GDB1653	13.0460-4976.2	z czujnikiem
223	33222	Opel Astra J 09-> , Chevrolet Cruze 09-> , tył, z ze	GDB1844	13.0460-7264.2	z zest.mont. (109-1813)
224	33223	Renault Master II 98-> , Iveco Daily III 99-> , czuj.	GDB1610	13.0460-4847.2	z czujnikiem
225	33224	Iveco Daily III 99-> , Iveco Daily IV 06-> tył, z zest	GDB1748	13.0460-4823.2	z zest.mont. (109-1600 + 4 śruby + 4 kapturki)
226	33225	Iveco Daily III 99-> , Iveco Daily IV 06-> tył, czuj.	GDB1535	13.0460-4996.2	z czujnikiem
227	33226	Peugeot 207 06-> , tył	GDB1678	13.0460-3851.2	
228	33227	Peugeot 308 07-> , Peugeot 3008 09->	GDB1761	13.0460-3847.2	
229	33228	Citroen C5 08-> , Peugeot 407 04-> , czuj.	GDB1818	13.0460-7252.2	
230	33229	Citroen Nemo 09-> , Peugeot Biper 08-> , z zest.	GDB1891	13.0460-3863.2	Z czujnikiem, z zest.mont. (109-1298 + 2 śruby)
231	33230	Citroen Berlingo 08-> , Peugeot 308 SW 07-> , tył	GDB1799	13.0460-2745.2	
232	33231	Citroen C4 09-> , Peugeot Partner 08->	GDB1690	13.0460-7229.2	
233	33232	Opel Astra J 09-> , Chevrolet Cruze 09-> , z zest.	GDB1847	13.0460-7263.2	z zest.mont. (109-1813)
234	33233	Opel Insignia 08-> , SAAB 9-5 10-> , z zest.	GDB1783	13.0460-5612.2	z czujnikiem akustycznym, jak w klockach BOSCH 0986494632
235	33234	Opel Insignia 08-> , SAAB 9-5 10-> , z zest.	GDB1782	13.0460-5611.2	z czujnikiem akustycznym, jak w klockach BOSCH 0986494632
236	33235	Citroen Jumpy 07-> , Fiat Scudo 07-> , Peugeot Ex	GDB1719	13.0460-2738.2	Z czujnikiem, z zest.mont. (109-1716 + 2 śruby)
237	33236	Citroen Jumpy 07-> , Fiat Scudo 07-> , Peugeot Ex	GDB1740	13.0460-2739.2	z zest.mont. (109-1716 + 2 śruby)
238	33237	Hyundai i30 07-> , KIA Sportage 04-> , tył, z zest.	GDB3421	13.0460-5780.2	z zest.mont. (109-1734)
239	33238	Hyundai ix35 09-> , KIA Sportage 04->	GDB3461	13.0460-5600.2	
240	33239	Hyundai Getz 03-> , KIA Sportage 04-> , tył	GDB3284	13.0460-5833.2	
241	33240	Volvo S60 00-> , Volvo S80 I 98->	GDB1576	13.0460-7187.2	
242	33241	Volvo XC90 02-> , tył	GDB1566	13.0460-7189.2	

Arkuszl

243	33242	Ford S-Max 06->, Volvo S60 II 10->	GDB1684	13.0460-7243.2	
244	33243	Renault Laguna III 07->,	GDB1808	13.0460-7249.2	
245	33244	Dacia Duster 10->, Renault Megane III 08->	GDB1789	13.0460-7266.2	
246	33245	Renault Megane III 08->, Renault Scenic III 09->,	GDB1791		2 śruby
247	33246	Audi A3 03->, Skoda Octavia 04->, VW Golf VI 08->	GDB1841	13.0460-3858.2	4 śruby
248	33247	Infiniti FX 03->, Nissan X-Trail 01->, tył	GDB3294	13.0460-5843.2	
249	33248	Nissan X-Trail 01->	GDB3293	13.0460-5842.2	
250	33249	Nissan QASHQAI 07->, Nissan X-Trail 07->	GDB3467	13.0460-5752.2	
251	33250	Nissan Murano 03->, Nissan Navara 05->	GDB3404	13.0460-5783.2	
252	33251	Nissan Navara 04->, Nissan Pathfinder 05->, tył	GDB3405	13.0460-5784.2	
253	33252	Mitsubishi Outlander II 00->, Peugeot 4007 07->,	GDB3247	13.0460-5855.2	jak w klockach FEBI BILSTEIN 16583
254	33253	Dodge Caliper 06->, Mitsubishi Outlander 01->, z	GDB3287	13.0460-5760.2	z zest.mont. (109-1194), z blaszkami jak w ATE 13.0460-5760
255	33254	Mercedes Klasa A (W169) 04->, Mercedes Klasa	GDB1628	13.0460-2708.2	2 śruby
256	33255	Mercedes Klasa A (W169) 04->, Mercedes Klasa	GDB1630	13.0460-2711.2	z zest.mont. (109-1653 + 2 śruby)
257	33256	Mercedes Klasa A (W169) 04->, Mercedes Klasa	GDB1481	13.0460-2712.2	z zest.mont. (109-1147)
258	33257	Mercedes Klasa C (S203) 01->, Mercedes Klasa	GDB1543	13.0460-4984.2	z czujnikiem
259	33258	Mercedes Klasa C (W204) 07->, Mercedes Klasa	GDB1738		z czujnikiem
260	33259	Mercedes Klasa C (W204) 07->, Mercedes Klasa	GDB1736		z zest.mont. (109-1649 + 2 śruby)
261	33260	Mercedes Klasa E (W211) 02->, Mercedes Klasa	GDB1546	13.0460-7171.2	z czujnikiem
262	33261	Mercedes Klasa E (W211) 02->, z zest.	GDB1542	13.0460-3999.2	z 2 czujnikami, z zest.mont. (109-1234 + 2 śruby)
263	33262	Mazda 6 02->, z zest.	GDB3310	13.0460-5821.2	
264	33263	Mazda 6 02->, tył	GDB3311	13.0460-5804.2	
265	33264	Mazda 323 98->	GDB3209		
266	33265	Opel Astra J 09->, Chevrolet Cruze 09->	GDB1843	13.0460-7262.2	
267	33266	Iveco Daily III 99->, Iveco Daily IV 06->	GDB1345	13.0460-4966.2	z zest.mont. (109-1768)
268	33267	VW Transporter T5 03->, VW Touareg 02->, tył, z	GDB1671	13.0460-7218.2	z czujnikiem
269	33268	VW Transporter T5 03->, tył, z czuj.	GDB1557	13.0460-2882.2	Z czujnikiem, z zest.mont. (109-1610 + 4 śruby)
270	33269	Honda Accord IV 91->, Rover 600 83->, tył	GDB774	13.0460-5929.2	
271	33270	BMW X5 ( E70 ) 07->, BMW X6 ( E71,E72 ) 08->,	GDB1730	13.0460-7232.2	
272	33271	BMW 5 ( E39 ) 95->, BMW X3 ( E83 ) 04->,	GDB1261	13.0460-7078.2	
273	33272	Honda Civic V,VI,VII,VIII, Honda CR-Z 10->	GDB3375	13.0460-5820.2	
274	33273	Citroen C4 Grand Picasso 06->, Citroen C4 Picas	GDB1692	13.0460-3836.2	
275	33274	Citroen C4 II 09->, Peugeot 3008 09->	GDB1691	13.0460-7230.2	
276	33275	KIA Rio II 05->, Hyundai i20 08->	GDB3420	13.0460-5779.2	z zest.mont. (109-1735)
277	33276	Honda Civic VI 95->, Honda Jazz III 08->, tył	GDB3174		
278	33277	Honda Civic VII 99->	GDB3267	13.0460-5830.2	z czujnikiem akustycznym



Arkuszl

279	33278	Alfa Romeo 156 97->, Fiat Linea 07->, tył	GDB1396	13.0460-2867.2	
280	33279	Alfa Romeo 146 94->, Fiat Punto 94->	GDB458	13.0460-2949.2	z czujnikiem
281	33280	Alfa Romeo 159 05->, Lancia Delta III 08->, tył	GDB1649	13.0460-2707.2	z zest.mont. (109-1606 + 4 śruby)
282	33281	BMW 3 ( E90 ) 06->, BMW 1 ( E81 ) 04->	GDB1625	13.0460-7215.2	
283	33282	BMW 3 ( E90 ) 05->, BMW X1 ( E84 ) 09->, tył	GDB1560	13.0460-7225.2	
284	33283	BMW 3 ( E46 ) 00->, BMW X3 ( E83 ) 04->	GDB1531	13.0460-7155.2	
285	33284	BMW X5 ( E53 ) 00->, BMW 3 ( E46 ) 98->, tył	GDB1530	13.0460-7079.2	
286	33285	Toyota RAV 4 06->, Toyota Auris 06->	GDB3424	13.0460-5766.2	z zest.mont. (109-1748)
287	33286	Toyota RAV 4 06->, Lexus ES 12->, tył	GDB3426	13.0460-5765.2	
288	33287	Toyota Yaris 13->, Daihatsu Charade 11->	GDB3457	13.0460-7213.2	
289	33288	Toyota Avensis 09->, Toyota Corolla 06->	GDB3479	13.0460-5603.2	
290	33289	Toyota Auris 07->, Toyota Corolla 01->, tył	GDB3480	13.0460-5604.2	z zest.mont. (109-1298)
291	33290	Volvo C30 06->, Opel Vectra C 05->	GDB1607	13.0460-7204.2	
292	33291	Nissan Juke 10->, Suzuki SX4 06->	GDB1003	13.0460-5716.2	
293	33292	Nissan Juke 10->, Nissan Cube 06->, tył	GDB3508		
294	33293	Audi A4 07->, Audi Q5 08->	GDB1814	13.0460-7256.2	
295	33294	Audi A4 04->, Seat Exeo 08->	GDB1617	13.0460-7201.2	
296	33295	VW Phaeton 02->, tył z czyj.	GDB1508	13.0460-2890.2	
297	33296	Honda Accord VII 03→, Honda CR-V II 01→, tył	GDB3438		
298	33297	Dodge Caravan 00→, Chrysler Voyager 99→, tył	GDB4130	13.0460-8008.2	
299	33298	Renault Kango 08→, Mercedes Citan 12->	GDB1785	13.0460-2741.2	
300	33299	Toyota Auris 07->, Toyota Corolla 01->, tył	GDB3454	13.0460-5769.2	
301	33300	Opel Movano 10→, Nissan NV400 11->	GDB1910	13.0460-4856.2	
302	33301	VW Golf VII 12→, Audi A3 12→	GDB1956		z czujnikiem, 4 śruby
303	33302	Renault Clio IV 12→, Dacia Logan II 12→	GDB2016		
304	33303	Toyota Auris 07→,	GDB3481	13.0460-5602.2	z zest.mont. (109-1298)
305	33304	Toyota Avensis Verso 01->	GDB3315	13.0460-5846.2	
306	33305	Toyota Avensis Verso 01→, tył	GDB3249	13.0460-5847.2	
307	33306	Alfa Romeo 159 05->, Alfa Romeo Spider 06->	GDB1647	13.0460-7211.2	
308	33307	Alfa Romeo MITO 08→, tył	GDB1881	13.0460-2763.2	
309	33308	Alfa Romeo MITO 08→, Fiat Bravo II 06→	GDB1484	13.0460-3984.2	z czujnikiem, 4 śruby
310	33309	Alfa Romeo MITO 08→, Fiat Bravo II 06→, tył	GDB1485	13.0460-3991.2	4 śruby
311	33310	Alfa Romeo MITO 08→, Fiat Bravo II 06→ „ukł.	GDB1855		
312	33311	Audi A4 07→, Audi A5 07→	GDB1768	13.0460.2746.2	z czujnikiem, 4 śruby
313	33312	VW Golf VII 12→, Audi A3 12→, tył	GDB1957		
314	33313	Audi A6 04→, VW Passat 10→, tył	GDB1763	13.0460-2749.2	z zest.mont. (109-1606 + 4 śruby)

Arkusz1

315	33314	BMW 5 ( F10 ) 10→, BMW 5 ( F11 ) 10→	GDB1882	13.0460-7268.2	
316	33315	BMW 5 ( F10 ) 10→, BMW 6 ( F13 ) 10→	GDB1838	13.0460-7267.2	z czujnikiem
317	33316	BMW X5 ( E70 ) 07→, BMW X6 ( E71 ) 08→, tył	GDB1502	13.0460-7169.2	z czujnikiem
318	33317	Citroen C5 I 01→, Citroen C5 II 05→	GDB1449	13.0460-3998.2	z czujnikiem
319	33318	Honda Accord 97→, Honda Accord VII 02→, tył	GDB3190	13.0460-5827.2	jak w klockach ABS 37175
320	33319	Honda Accord VII 02-08	GDB3355	13.0460-5714.2	
321	33320	Honda Accord VIII 08→, przód	GDB3476		2 śruby
322	33321	Honda Accord VIII 08→, tył	GDB3482		
323	33322	Honda CR-V 06→, Honda CR-V 12→	GDB3445	13.0460-5753.2	z zest.mont. (109-1298 + 2śruby)
324	33323	Honda CR-V 06→, Honda CR-V 12→, tył	GDB3446	13.0460-5754.2	z zest.mont. (109-1298 + 2śruby)
325	33324	Hyundai i30 11→, KIA Soul 09→, tył	GDB3494	13.0460-5786.2	z czujnikiem akustycznym, z zest.mont., ( 109-1734)
326	33325	Citroen C5 I 01→, Citroen C5 II 05→	GDB1447	13.0460-3996.2	z czujnikiem
327	33326	BMW 3 ( E90 ) 05→, BMW 5 ( E60 ) 03->	GDB1498	13.0460-7167.2	
328	33327	BMW 3 ( E90 ) 05→, BMW X1 ( E84 ) 09->	GDB1729	13.0460-7238.2	
329	33329	Audi A6 04→, VW Phaeton 02->	GDB1553	13.0460-7182.2	
330	33330	Land Rover Discovery III 04→, tył	GDB1632	13.0460-2719.2	z zest.mont. (109-1728)
331	33331	Land Rover Discovery III 04→	GDB1631	13.0460-2728.2	z zest.mont. (109-1728)
332	33332	Jeep Cherokee 01→, Jeep Wrangler II 96→, tył	GDB4139		
333	33333	Nissan Navara 04- >, Renault Koleos 08- >	GDB3392	13.0460-5778.2	
334	33334	BMW X5 ( E70 ) 07->, BMW X6 ( E71 ) 08->	GDB1726	13.0460-7231.2	
335	33335	BMW 1 ( E81 ) 04- >, Mini 01- >	GDB1611	13.0460-2710.2	
336	33336	Iveco Daily III 06->	GDB1747	13.0460-4830.2	
337	33337	Toyota Avensis 09→, tył	GDB4175	13.0460-3853.2	
338	33338	Landrover Freelander 00->	GDB1473	13.0460-2718.2	
339	33339	Hyundai Santa Fe 01- >	GDB3297	13.0460-5832.2	
340	33340	Fiat Grande Punto 07- >, tył	GDB1656	13.0460-3828.2	
341	33341	Kia Sportage 04- >, Hyundai Elantra 00- > ,	GDB3386	13.0460-5873.2	z czujnikiem akustycznym
342	33342	Audi A4 07- >, Audi A5 09- > tył	GDB1765	13.0460-2747.2	z zest.mont. (109-1766)
343	33343	VW Touareg 10- >, Porsche Cayenne 10→, tył	GDB1875	13.0460-4872.2	
344	33344	Citroen DS4 11- >, Peugeot 5008 09 - >, tył	GDB1828	13.0460-2761.2	z zest.mont. (109-1211 + 4 śruby)
345	33345	Mercedes Klasa B 11- >, Mercedes SLK 11- >, tył	GDB1920	13.0460-2786.2	
346	33346	CITROEN JUMPER 06->, FIAT DUCATO 06->	GDB1681	-4807.2 / 13.0460	2 czujniki i zestaw montażowy , ( 109-1725 i 109-1726 )
347	33347	BMW 5 ( F10 ) 10->, BMW X3 ( F25 ) 10->, TYŁ	GDB1840	13.0460-2760.2	z zest.mont., ( 109-1828 )
348	33348	AUDI A6 11->, AUDI A7 10->	GDB1897	13.0460-7280.2	
349	33349	BMW 3 ( F30 ) 12->, BMW 4 ( F32 ) 13->, TYŁ	GDB1919	13.0460-3859.2	
350	33350	BMW X3 ( F25 ) 10-> ,BMW 3 ( F30 ) 11->	GDB1942	13.0460-3857.2	

Arkusz1

351	33351	OPEL INSIGNIA 08->, 18" KOŁO	GDB1781	13.0460-2754.2	z czujnikiem akustycznym, z zest.mont., ( 109-1788 )
352	33352	HYUNDAI SANTA FE 06->	GDB3418	13.0460-5777.2	z czujnikiem akustycznym, z zest.mont., ( 109-1719 )
353	33353	TOYOTA CAMRY 06->	GDB3429	13.0460-5764.2	
354	33354	KIA K2500 03->	GDB3434		
355	33355	mitsubishi L200 06->, MITSUBISHI PAJERO 9	GDB3435	13.0460-5631.2	z zest.mont., ( 109-1769 )
356	33356	SUZUKI GRAND VITARA 05->	GDB3436	13.0460-5609.2	z czujnikiem akustycznym, z zest.mont., ( 109-1244 )
357	33357	NISSAN CABSTAR 06->	GDB3439	13.0460-4866.2	z czujnikiem, z zestawem montazowym, ( 109-1768 )
358	33358	NISSAN CABSTAR 06->, TYŁ, ŁADOWNOŚĆ 45	GDB3440	13.0460-4861.2	z czujnikiem, z zestawem montazowym, ( )
359	33359	NISSAN CABSTAR 06->, TYŁ, ŁADOWNOŚĆ 3	GDB3441	13.0460-4859.2	z czujnikiem, z zest.mont., ( )
360	33360	SUBARU TRIBECA 05->, SUBARU FORESTER	GDB3442		
361	33361	KIA CARNIVAL 06->, HYUNADIA H1- CARGO 08	GDB3448	13.0460-5799.2	z czujnikiem akustycznym, z zest.mont., ( 109-1744 )
362	33362	KIA CARNIVAL 06->, HYUNADIA H1- CARGO 08	GDB3449	-5771.2 / 13.0460	z czujnikiem akustycznym, z zest.mont., ( 109-1758 )
363	33363	KIA SORENTO 02->	GDB3343	13.0460-5772.2	z czujnikiem akustycznym, z zest.mont., ( 109-1664 )
364	33364	TOYOTA YARIS 06->, DAIHATSU CHARADE 11	GDB3458	13.0460-7214.2	
365	33365	TOYOTA YARIS 06->	GDB3459		
366	33366	KIA CARENS II 02->, KIA CARENS III 06->	GDB3462	13.0460-5601.2	z czujnikiem akustycznym, z zest.mont., ( 109-1652 )
367	33367	MAZDA CX-7 06->, MAZDA CX-9 07->	GDB3471	13.0460-5606.2	z zest.mont., ( 109-1775 )
368	33368	MAZDA CX-7 06->, MAZDA CX-9 07->, TYŁ	GDB3472	13.0460-5605.2	z zest.mont., ( 109-1720 )
369	33369	HONDA ACCORD 08->	GDB3477		
370	33370	SUZUKI GRAND VITARA 05->	GDB3490		
371	33371	MITSUBISHI CANTER 06->, PRZÓD I TYŁ	GDB3492		
372	33372	HONDA JAZZ 09->	GDB3493	13.0460-5620.2	
373	33373	KIA SORENTO 09->, HYUNDAI SANTA FE II 06-	GDB3499	13.0460-5633.2	z czujnikiem akustycznym, z zest.mont., ( 109-1717 )
374	33374	TOYOTA HILUX 06->	GDB3500	13.0460-5616.2	
375	33375	MAZDA 6 07->	GDB3501	13.0460-5610.2	z czujnikiem akustycznym, z zest.mont., ( 109-1791 )
376	33376	TOYOTA AURIS 12->, TOYOTA COROLLA 06->	GDB3598		
377	33377	MAZDA 3 13->, TYŁ	GDB3593		
378	33378	MAZDA 3 13->	GDB3592		
379	33379	MAZDA 6 12->, TYŁ	GDB3583		z czujnikiem akustycznym, z zest.mont., ( 109-1896 )
380	33380	KIA CEED 12->, HYUNDAI I30 11->	GDB3582		z czujnikiem akustycznym, z zest.mont., ( 109-1708 )
381	33381	MAZDA 6 12->	GDB3580		z zest.mont., ( 109-1748 )
382	33382	CHEVROLET AVEO 11->, CHEVROLET COBAL	GDB3579		z czujnikiem akustycznym, z zest.mont., ( 109-1813 )
383	33383	OPEL ANTARA 06->, CHEVROLET CAPTIVA 11	GDB3566	13.0460-5788.2	z czujnikiem akustycznym, z zest.mont., ( 109-1704 )
384	33384	MAZDA CX-5 11->	GDB3562		
385	33385	OPEL ANTARA 06->, CHEVROLET CAPTIVA 06	GDB1715	13.0460-5785.2	z czujnikiem akustycznym, z zest.mont., ( 109-1761 )
386	33386	BMW X5 ( E70 ) 07->, BMW X6 ( E71 ) 08->	GDB1728	13.0460-7239.2	

Arkusz1

387	33387	MERCEDES E KLASA ( W211 ) 02->, MERCEDE	GDB1733	13.0460-4817.2	
388	33388	MERCEDES C-KLASA (W204 ) 07->, MERCEDE	GDB1737	13.0460-2734.2	z zest.mont., ( )
389	33389	VOLVO XC90 02->, KOŁA 17"	GDB1565	13.0460-7188.2	
390	33390	VOLVO XC60 08->, VOLVO XC 70 II 07->	GDB1821	13.0460-7272.2	
391	33391	BMW 5 ( F10 ) 10->, BMW 6 ( F13 ) 10->, TYŁ	GDB1869	13.0460-2716.2	z zest.mont., ( 109-1828 )
392	33392	ALFA ROMEO GIULIETTA 10->	GDB1880	13.0460-7269.2	
393	33393	VW TRANSPORTER T5 09->	GDB1887	13.0460-7286.2	z zest.mont., ( 109-1680 )
394	33394	PEUGEOT 407 09->	GDB1895	13.0460-2891.2	
395	33395	CITROEN C3 PICASSO 09->, PEUGEOT 2008 1	GDB1926	13.0460-3855.2	
396	33396	MERCEDES A-KLASA ( W176 ) 12->, MERCEDE	GDB1932	13.0460-2779.2	
397	33468	Mercedes Klasa M( W166 ) 11->, tył	GDB1947	13.0460-2781.2	
398	33397	FORD B-MAX 12->, FORD FIESTA VI 12->	GDB1959	13.0460-2784.2	z zest.mont., ( 109-1861 )
399	33398	TOYOTA AVENSIS 97->, LEXUS ES 89->, TYŁ	GDB1168	13.0460-5835.2	
400	33432	Fiat 500 07->, Ford KA 08->	GDB1745	13.0460-3838.2	z czujnikiem, z zest.mont. ( 109-1273 )
401	33399	FIAT DUCATO 14->, TYŁ	GDB2068		
402	33400	Alfa Romeo 159 05- >, Lancia Kappa 94- >	GDB1648	13.0460-4851.2	z czujnikiem
403	33401	Mazda 6 02- >	GDB3309	13.0460-5822.2	z czujnikiem akustycznym
404	33402	KIA Carens 00- >, KIA Shuma 97- >, tył	GDB3203	13.0460-5871.2	z czujnikiem akustycznym
405	33403	Lexus LS 06- >	GDB3473	13.0460-5607.2	
406	33404	Lexus LS 06- >, tył	GDB3475	13.0460-5608.2	
407	33405	Lexus LX 07- >, Toyota Land Cruiser 07- >, tył	GDB3491	13.0460-5619.2	
408	33406	Hyundai ix20 10- >, KIA Venga 10- >	GDB3509	13.0460-2772.2	z czujnikiem akustycznym
409	33407	Hyundai i20 08- >	GDB3510	13.0460-5776.2	z czujnikiem akustycznym
410	33408	Hyundai i40 11- >, KIA Sportage 10->	GDB3530		
411	33409	KIA Picanto 11- >	GDB3535	13.0460-5649.2	
412	33410	Mazda CX-5 11- >, tył	GDB3539		z czujnikiem akustycznym
413	33411	Nissan Micra 10- >, Nissan Note 13- >	GDB3546	13.0460-2774.2	z czujnikiem akustycznym
414	33412	Hyundai Accent IV 10- >, KIA Rio III 11- >	GDB3548	13.0460-5646.2	z czujnikiem akustycznym
415	33413	Hyundai ix20 10- >, Hyundai Sonata 09- >	GDB3553	13.0460-5641.2	z czujnikiem akustycznym
416	33414	Chrysler Grand Voyager 07- >, Fiat Freemont 11-	GDB4176	13.0460-2771.2	z czujnikiem akustycznym
417	33415	Chrysler Grand Voyager 07- >, Fiat Freemont 11-	GDB4605	-2766.2 / 13.0460	z czujnikiem akustycznym
418	33416	Opel Frontera A i B , Isuzu Trooper 00->, tył	GDB1187	13.0460-5927.2	z czujnikiem akustycznym
419	33417	Land Rover Defender 07- >, tył	GDB1666	13.0460-6924.2	
420	33418	Chrysler Neon 94- >, Dodge Caravan 95- >	GDB1236	13.0460-8003.2	
421	33419	Mercedes Klasa A ( W168 ) 97- >	GDB1293	-2776.2 / 13.0460	-2833.2
422	33420	Citroen C2 03- >, Citroen C3 02- >	GDB1496	13.0460-2881.2	

Arkuszl

423	33421	Audi A6 97- >, Skoda Fabia 00- >	GDB1528	13.0460-7166.2	z czujnikiem
424	33422	VW Touareg 04- >, Porsche Cayenne 02- >	GDB1547	13.0460-4992.2	
425	33423	VW Touareg 02- >	GDB1670	13.0460-4833.2	
426	33424	Fiat Sedici 06- >, Suzuki SX4 06- >	GDB1673	13.0460-2715.2	z czujnikiem akustycznym
427	33425	VW Golf VII 12- >, Skoda Octavia 12- >	GDB2080	13.0460-7303.2	z czujnikiem
428	33426	Porsche Cayenne 10- >	GDB2004		
429	33427	Nissan Almera 02- >, Nissan Primera 02- >	GDB3227	13.0460-5825.2	
430	33428	Mercedes Citan 12- >, Renault Kangoo 05- >, tył	GDB1786	13.0460-2744.2	
431	33429	Iveco Daily IV 06- >, Iveco Daily V 11- >, tył	GDB1780	13.0460-4829.2	
432	33430	Audi Q7 06- >, VW Touareg 06- >, tył	GDB1775	13.0460-4850.2	
433	33431	VW Touareg 02- >, tył	GDB1722	13.0460-4834.2	
434	33433	Rover 75 99->, MG 6 10->	GDB1374	13.0460-7144.2	
435	33434	Fiat Doblo 10->, Opel Combo 12->	B1864 / GDB1	13.0460-7265.2	z czujnikiem
436	33435	Audi Q3 11->, VW Tiguan 10->	GDB1762	13.0460-7242.2	z czujnikiem
437	33436	Mini Cooper 06->, tył	GDB1766	13.0460-2714.2	
438	33437	Mercedes Klasa A ( W176 ) 12->, Mercedes Klasa	GDB1933	13.0460-2778.2	
439	33438	Renault Traffic 14->, Opel Vivaro 14->	GDB2096		
440	33439	Daewoo Lacetti 04->, Chevrolet Aveo 05->, tył	GDB3348	13.0460-5739.2	
441	33440	Opel Corsa E 14->	GDB2099		
442	33441	Skoda Octavia 12->, Seat Leon 12->, tył	GDB2042	13.0460-2790.2	
443	33442	Opel Astra K 15->, felgi 15"	GDB2138		
444	33443	Opel Astra K 15->, felgi 16"	GDB2139		
445	33444	Ford Kuga II 13->, Ford Focus III 11->	GDB2009		
446	33445	Citroen C4 II 09->, Citroen DS4 11->,	GDB1917		
447	33446	Suzuki Swift IV 10, tył	GDB3529		
448	33447	Hyundai i30 11->, KIA Ceed 12->	GDB3549		
449	33448	Fiat Panda 12->, Lancia Ypsilon 03->	GDB1921	13.0460-7289.2	
450	33449	BMW 1 ( F20 ) 10->, BMW 3 ( F30 ) 11->	GDB1934	13.0460-3866.2	
451	33450	BMW 1 ( F20 ) 10->, BMW 2 ( F22 ) 13->	GDB1935	13.0460-3865.2	
452	33451	Citoren C4 Picasso II 13->, tył	GDB2034	13.0460-3872.2	
453	33452	Citroen C4 Picasso 13->, Peugeot 308 II 13->, tył	GDB2036	13.0460-3871.2	
454	33453	Toyota Aygo 05->, Citroen C1 II 14->	GDB1633	13.0460-3829.2	
455	33454	Peugeot 308 II 13->,	GDB2044	13.0460-3870.2	
456	33455	Ford Focus III 11->, Ford C-Max II 15->	GDB2059		
457	33456	Fiat Ducato 14->,	GDB2069		

Arkusz1

458	33457	Opel Corsa E 14->, Opel Adam 12->	GDB2091		
459	33458	Ford Mondeo 14->	GDB2092		
460	33459	KIA Sorento 15->, tył	GDB2112		
461	33460	Renault Megane III 08->, Renault Grand Scenic II	GDB1790	13.0460-7249.2	
462	33461	Mitsubishi Outlander II 06->, Peugeot 4007 07->	GDB1126	13.0460-5958.2	
463	33462	Fiat Tipo 15->	GDB2151		
464	33463	Fiat Tipo 15-> tył	GDB2156		
465	33464	Renault Laguna III 07->	GDB1788	13.0460-7250.2	
466	33465	Hyundai i10 13->	GDB3618	13.0460-5653.2	
467	33466	Mazda 6 12->, „ kombi”, tył	GDB3632		
468	33467	BMW 3 F30 11->, BMW 4 F32,F82 13->, tył	GDB1937		
469	33469	Renault Sandero 13->, Dacia Logan II 12->	GDB2018	13.0460-7298.2	
470	33470	Skoda Fabia 07-> ,	GDB2027		
471	33471	Citroen C4 Grand Picasso II 13->, Peugeot 308 II	GDB2035	13.0460-7300.2	
472	33472	VW Passat 15->, VW Caddy IV 15->	GDB2143	13.0460-2609.2	
473	33473	KIA Sorento III 15->	GDB3638		
474	33474	Jeep Grand Cherokee IV 10- >	GDB4603	13.0460-7282.2	
475	33475	Opel Astra K 15 - >, tył	GDB2180	13.0460-2615.2	
476	33476	Renault Megane IV 15- >	GDB2175		ze śrubami
477	33477	Dacia Sandero 15→, Renault Clio IV 12→	GDB2157		

**Numery TRW, ATE, Bosch, Febi, Quick Brake i inne zostały użyte tylko do porównania**